

CONTRACT DATA REQUIREMENTS LIST (1 Data Item)						Form Approved OMB No. 0704-0188			
Public reporting burden for this collection of information is estimated to average 110 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503. Please DO NOT RETURN your form to either of these addresses. Send completed form to the Government Issuing Contracting Officer for the Contract/PR No. Listed in Block E.									
A. CONTRACT LINE ITEM NO.		B. EXH/ATCH NO.		C. CATEGORY:					
				TDP TM OTHER					
D. SYSTEM/ITEM LM2500 High Speed Coupling Shaft (HSCS)			E. CONTRACT/PR NO.		F. CONTRACTOR				
1. DATA ITEM NO. 0001		2. TITLE OF DATA ITEM HSCS Refurbishment Report			3. SUBTITLE		17. PRICE GROUP		
4. AUTHORITY (Data Acquisition Document No.)				5. CONTRACT REFERENCE Statement of Work		6. REQUIRING OFFICE NSWCCD 9333			
7.		9. DIST STATEMENT REQUIRED A		10. FREQUENCY ASREQ		12. DATE OF FIRST SUBMISSION See Block 16			
8. ADP CODE				11. AS OF DATE		13. DATE OF SUBSEQUENT SUBMISSION			
						14. DISTRIBUTION			
						a. ADDRESSEE		b. COPIES	
								Draft Final	
16. REMARKS The LM2500 HSCS Refurbishment Report is acceptable in the contractor's format. The report shall at a minimum detail the following information: *Disassembly inspection results *Repairs made to each sub-assembly; the forward adapter, aft adapter, and distance piece. *Non-destructive test results *Balance results of the forward adapter, aft adapter, and final assembled HSCS *Complete parts replacement list *Digital pictures of all sub-assemblies and final assembled HSCS in the final refurbished state Blk 12: Submit the HSCS Refurbishment Report within 30 days after refurbishment completion						NSWCCD 9333		Reg Repro	
						15. TOTAL			
G. PREPARED BY <i>E. Jantzen</i>			H. DATE 13 Jan 04		I. APPROVED BY		J. DATE		

Attachment 2